


# MOISTURE METER

(Search type)

## AM-128S

This Moisture Meter is small in size, light in weight, easy to carry. Although complex and advanced, it is convenient to use and operate. Its ruggedness will allow many years of use if proper operating techniques are followed. Please read the following instructions carefully and always keep this manual within easy reach.

### 3. FRONT PANEL DESCRIPTIONS



- |                          |                                 |
|--------------------------|---------------------------------|
| 3-1 Search probe         | 3-7 Select key                  |
| 3-2 Display              | 3-8 Power/Menu key              |
| 3-3 Data cable interface | 3-9 Delete key                  |
| 3-4 Color coded LED      | 3-10 Read key                   |
| 3-5 Plus key             | 3-11 Measure key                |
| 3-6 Minus/Zero key       | 3-12 Battery compartment/ Cover |

## TABLE OF CONTENTS

1. FEATURES .....	1
2. SPECIFICATIONS .....	1
3. FRONT PANEL DESCRIPTIONS .....	3
4. MEASURING PROCEDURE .....	4
5. STATISTICS .....	5
6. STORING AND RECALLING READINGS .....	5
7. DELETING READINGS .....	6
8. ALARM LIMITS .....	6
9. CONSIDERATIONS .....	7
10. BATTERY REPLACEMENT .....	7
11. TRANSFERRING READINGS TO A COMPUTER .....	7
12. APPENDIX .....	9

### 4. MEASURING PROCEDURE

- 4.1 Depress the 'power key' and release to power on the meter.
- 4.2 To check if the material code is right by pressing and releasing the 'Select key'. Such code can be changed by the 'Plus key' or 'Minus/Zero key' when the 'cdxx' is on the display. Here 'cd' is the abbreviation for 'code' and 'xx' is the material no. If keep depressing the 'Plus' or 'Minus/Zero key', the material code will step into next code about every second and releasing it till the material code is right.
- 4.2.1 Code selection
- The standard material code for the search mode is 'cd10' which is suitable for measuring the material whose density is like that of pine, fir, oak etc. The user can carry out the accurate measurement by selecting one material code between 'cd01' and 'cd20'. The greater the density of the material to be measured, the larger the material code to be selected. For measuring moisture in concrete wall, the user can select the code around 'cd18'. Please refer the Appendix on page 9 when selecting the code. This code is only for reference due to many uncertain factors for materials to be measured.
- 4.2.2 Factors affecting the choice of material code
- There are many factors to affect the material code, for instance, different places, different soil even if in a same place will lead to different code for a same material. The better way to

### 1. FEATURES

- \* Be a powerful and versatile instrument for measuring and diagnosing dampness in buildings and building materials. This product enables building surveyors and other practitioners to measure moisture levels of building elements such as walls, floors and other building materials simply by switching between the two different modes of operation. In this way, a detailed understanding of the moisture condition of the property can be obtained.
- \* Digital display gives exact reading with no guessing or errors while a colour coded light (LED) indicates the moisture condition of the materials. This combined presentation of moisture measurement helps the user to map the extent of problems and monitor changes in condition precisely and reliably.
- \* Used the exclusive Micro-computer LSI circuit and crystal time base to offer high accuracy measurement.
- \* Wide measuring range and high resolution.
- \* Automatic power off to conserve power.
- \* Can communicate with PC computer for statistics and printing by the optional cable and software for USB interface.
- \* Can store 240 groups of measurement results with statistical functions.

### 2. SPECIFICATIONS

- Display 4 digits, 10 mm LCD
- With colour coded LED indication
- Green LED represents a safe, air-dry state.

- ascertain the material code is based on standard tests by oven-drying of commercial samples of the material to be measured. The code by which the measuring results are closest to those of oven-drying method is the right code. Write down the code for such material for later uses.
- 4.3 Moisture measurement
- 4.3.1 Place the search probe against the surface of the material such as wall, floor etc. at the point of measurement.
- 4.3.2 Read the moisture level value from the display and note the moisture condition of the material from the colour coded LED.
- 4.4 Zero calibration
- The zero feature enable the user to compensate for the effect of changes in both temperature and humidity. Zero calibration should be carried out independently in different modes.

### 5. STATISTICS

- The gauge calculates and displays a statistical analysis of readings as they are taken. The statistics available are:
- \* Last value
  - \* Mean value marked by Ave
  - \* Highest Reading marked by Max.
  - \* Lowest Reading marked by Min.
  - \* Number of Readings taken
- When stored data exceed 99 groups, the latest value will be memorized, while the earliest one will be deleted, and so on.

### 6. STORING AND RECALLING READINGS

- 6.1 Readings taken are automatically saved to

- Yellow LED represents a borderline State.
- Red LED represents a damp state.
- Measuring range:  
0~70%(when code=cd10)
- Measuring code:  
20 codes for different materials
- Accuracy:  $\pm(0.5\%n+1)$
- PC interface: USB interface
- Power supply: 4x1.5 AAA size (UM-4) battery
- Power off: 2 modes
  - Manual off at any time
  - Auto power off after 5 minutes from last key operation
- Operating conditions:
  - Temperature: 0~50°C (32~122°F)
  - Humidity: < 90% RH
- Dimensions:
  - Main unit: 140x70x31mm 5.5x2.8x1.2inch
  - Contact area of sensor: 40x16mm
- Weight: 130g (not including batteries) 4.59oz
- Standard accessories included:
  - Carrying case 1 pc.
  - Operation manual 1 pc.
- Optional accessory
  - Cable and software for USB


- the memory of the gauge. The memorized data can be browsed by pressing and releasing the 'Read key' to enter into the browsing state marked by "RD" on the display.
- 6.2 In the browsing state, all the readings memorized can be recalled on the display by depressing the 'Plus key' or the 'Minus/Zero key'.
- 6.3 To delete singly a memorized value in the memory, just locate the reading to be deleted by the key 'Plus key' or 'Minus/Zero key', then press and release the 'Delete key'. If there is an 'Err0' on the display, it indicates there is no reading to delete any more.
- 6.4 To quit to the measurement state, just depress the 'Zero key'.
7. DELETING READINGS
- 7.1 To delete a reading on the display, just press the 'Delete key' no matter in the measurement state marked 'SV' or in the browsing state marked by 'RD'. Go into the browsing state by 'RD'. Go into the browsing state by pressing the 'Read key'.
- 7.2 To delete all the readings in the memory, just depress the 'Delete key' in the measurement state marked by "SV" on the display for about 5 seconds till the number of readings memorized becomes 0.
8. ALARM LIMITS
- 8.1 There is a coded coloured LED indicating the status of moisture. It is controlled by 2 alarm limits. The factory settings are as follow.

AL1=13 and AL2=18  
If the reading<AL1, the green LED is on.  
If the reading>AL2, the red LED is on.  
If the reading lies between AL1 and AL2, the yellow LED is on.  
Users can change the alarm limits when as per their intention.  
8.2 How to set the alarm limits  
8.2.1 Depress 'Select key' and not release it till 'AL1' 'AL2' appears on the Display. It is about 3 seconds from starting depressing the 'Select key'.  
8.2.2 Such value can be changed to your intended Value by depressing the 'Plus key' or 'Minus key'.  
. Depress the Select key to return to the state of measurement. If the second limit AL2 is less than the first limit AL1, the setting is invalid and the factory settings for AL1 and AL2 are restored to AL1=13 and AL2=18 automatically.

**9. CONSIDERATIONS**

9.1 Please keep it in a dry, dustproof place.  
9.2 The measurement result may be different if taking the measurement from different directions of the surface. That is because water in the material is not distributed evenly.

**10. BATTERY REPLACEMENT**

10.1 When it is necessary to replace the battery, the battery symbol '  ' will appear on the display.  
10.2 Slide the Battery Cover ( 3-4) away from the instrument and remove the batteries.  
10.3 Install the batteries (4x1.5vAAA/UM-4) correctly into the case.  
10.4 If the instrument is not used for a extended

period, remove batteries.  
**11. TRANSFERRING READINGS TO A COMPUTER**  
11.1 Install the software on your PC, please always click 'the continue' button in the installing process.  
11.2 Connect your gauge to your PC using the optional cable.  
11.3 Switch on your gauge and ensure the Reading Screen is displayed.  
11.4 Start the software and follow the instructions included with the software Demo.EXE.

**12. APPENDIX**

Density-Code table (only for reference)

Density	Code	Material
Kg/m³		(Only for reference)
200	1	
220	2	
240	3	Foam
320	4	Soft wood
400	5	Felt
440	6	Peat
480	7	Charcoal
520	8	
560	9	Coke
600	10	White lime
800	11	Veneer
1000	12	Timber, Chipboard
1200	13	Leather, Slag, Kerosene, Alcohol
1400	14	Polyethylene
1600	15	Soft coal, Bamboo, Paraffin
1800	16	ABS
2000	17	Clunch, Organic glass
2200	18	Asphaltum, lime
2500	19	Bakelite, fiberboard
3000	20	Rubber
		Stone, Sand (dry)
		Clayey brick
		Asbestine board
		Vitriol ( 87%)
		Sand (wet)
		Bricklaying, Firebrick
		Quartz glass
		Concrete, Asbestos, plaster
		China, Glass
		Magnetite, Granite, Marble

Specifications to change without notice  
NOTICE: WE ARE NOT RESPONSIBLE FOR  
TYPOGRAPHICAL ERRORS